

Flood Control Project Maintenance
2016 Structure Summary Report
Overall Unit and Item Ratings

Reclamation District No. 2096 Wetherbee Lake

Wetherbee Lake Pumping Plant & Navigation Gate

| Overall Unit Rating | Rated Item | Item Rating |
|---------------------|---------------------------------------|-------------|
| A | Operating Log | A |
| | Operation & Maintenance Manual | A |
| | Plant Building | A |
| | Communications | A |
| | Safety | M |
| | Cranes | N |
| | Pumps | A |
| | Power | A |
| | Motors, Engines, Fans & Gear Reducers | A |
| | Pump Control Systems | A |
| | Sumps/Wet Well | A |
| | Trash Racks | M |
| | Trash Rakes | N |
| | Sluice / Slide Gates | N |
| | Electric Gate Operators | A |
| | Manual Gate Operators | A |
| | Other Metallic Items | A |
| | Flap Gates | A |
| | Closure Structures | A |
| | Security Fencing | A |
| | Intake and Discharge Pipes | A |

Flood Control Project Maintenance**Unit Cover Sheet****2016 Pumping Plant Inspection Results****Reclamation District No. 2096 Wetherbee Lake**

| Pumping Plant |
|--|
| Wetherbee Lake Pumping Plant & Navigation Gate |

| | |
|----------------------|-------------------------|
| Pumping Plant Rating | A |
| Date of Inspection | 7/21/2016 |
| DWR Inspector | Maksim Khashchuk |
| Accompanied By | Randy Barker RD 2096 |

**Flood Control Project Maintenance
Levee Inspections**


Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | |
|---|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 1 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Operating Log | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298427 ° | -121.298427 ° |
| DWR ID | DWR_RD2096_56_t_2012_1 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: O&M log presented at time of inspection | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_1_20160729_00014.jpg



View of the Operating Log and O&M Manual.

| | | | | | |
|--|--------------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 2 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Operation & Maintenance Manual | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_2 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: O&M manual was present at time of inspection. LMA is in procees of creating posted operating instructions at pump station. | | | | | |

No Photos

| | | | | | | |
|--|------------------------|--------------|----|------------------------|---------------|--|
| LM Start | 0.00 | Rating ** | A | Issue No. | 3 | |
| LM End | 0.00 | Issue Type + | Ma | Location * | | |
| Category | Pump Stations | | | GPS Latitude/Longitude | | |
| | | | | Start | End | |
| Item | Plant Building | | | 37.773864 ° | 37.773864 ° | |
| | | | | -121.298430 ° | -121.298430 ° | |
| DWR ID | DWR_RD2096_56_t_2012_3 | | | | | |
| Action/Comments | | | | | | |
| Inspector Comments: Building protects the controls only. | | | | | | |

Photo 1 of 2 : ST_2016_RD2096_56_3_20160729_00025.jpg



View of the pant building and the radial gate.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | | |
|--|------------------------|--------------|----|------------------------|---------------|--|
| LM Start | 0.00 | Rating ** | A | Issue No. | 3 (cont) | |
| LM End | 0.00 | Issue Type + | Ma | Location * | | |
| Category | Pump Stations | | | GPS Latitude/Longitude | | |
| | | | | Start | End | |
| Item | Plant Building | | | 37.773864 ° | 37.773864 ° | |
| | | | | -121.298430 ° | -121.298430 ° | |
| DWR ID | DWR_RD2096_56_t_2012_3 | | | | | |
| Action/Comments | | | | | | |
| Inspector Comments: Building protects the controls only. | | | | | | |
| | | | | | | |

Photo 2 of 2 : ST_2016_RD2096_56_3_20160729_00015.jpg



View of the plant building.

| | | | | | |
|---|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 4 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Communications | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_4 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Trustee has cellular phone. | | | | | |

No Photos

| | | | | | |
|--|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | M | Issue No. | 5 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Safety | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_5 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Missing guard rail on navigation canal. Missing fire extinguisher. | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_5_20160729_00016.jpg



View of the missing guard rail.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | |
|--|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | N | Issue No. | 6 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Cranes | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_6 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Item does not apply, cranes are not present on site. | | | | | |

No Photos

| | | | | | | |
|--|------------------------|--------------|----|------------------------|---------------|--|
| LM Start | 0.00 | Rating ** | A | Issue No. | 7 | |
| LM End | 0.00 | Issue Type + | Ma | Location * | | |
| Category | Pump Stations | | | GPS Latitude/Longitude | | |
| | | | | Start | End | |
| Item | Pumps | | | 37.773864 ° | 37.773864 ° | |
| | | | | -121.298430 ° | -121.298430 ° | |
| DWR ID | DWR_RD2096_56_t_2012_7 | | | | | |
| Action/Comments | | | | | | |
| Inspector Comments: Pumps appear to be in working order. | | | | | | |
| | | | | | | |

No Photos

| | | | | | |
|---|------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 8 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Power | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_8 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: No electrical deficiencies observed. Backup generators can be brought in on an emergency basis. | | | | | |
| | | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | |
|---|---------------------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 10 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Motors, Engines, Fans & Gear Reducers | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_10 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: All items appear operational. | | | | | |

Photo 1 of 2 : ST_2016_RD2096_56_10_20160615_00004.jpg



Close up view of the pump motor.

| | | | | | |
|----------|-------------|--------------|----|------------|------------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 10 (cont) |
| LM End | 0.00 | Issue Type + | Ma | Location * | |

Photo 2 of 2 : ST_2016_RD2096_56_10_20160729_00017.jpg



View of the pump motors.

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 11 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Pump Control Systems | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_11 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Controls are free of damage and appear to operate normally. | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_11_20160729_00027.jpg



View of the water level monitoring system that automatically controls the pumps.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 12 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Sumps/Wet Well | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_12 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Sump is clear of debris. | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_12_20160729_00018.jpg



View of the pump intake system. Note the missing grate at top left corner.

| | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | M | Issue No. | 13 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trash Racks | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_13 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Trash rack is present, however one panel is missing from rack. | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_13_20160615_00006.jpg



Section of trash rack is missing, missing section would be in upper left of photo.

| | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | N | Issue No. | 14 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Trash Rakes | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_14 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: No trash rake present. | | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | N | Issue No. | 15 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Sluice / Slide Gates | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_15 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: No slide gates present | | | | | |

No Photos

| | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 16 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Electric Gate Operators | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_16 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Item appears to be in good working condition. Radial arm gate was open at time of inspection. | | | | | |

Photo 1 of 3 : ST_2016_RD2096_56_16_20160615_00008.jpg



View of the gate controls.

Photo 2 of 3 : ST_2016_RD2096_56_16_20160729_00019.jpg



View of the radial arm gate in the open position.

| | | | | | |
|----------|-------------|--------------|----|------------|------------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 16 (cont) |
| LM End | 0.00 | Issue Type + | Ma | Location * | |

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|--|
| LM Start | 0.00 | Rating ** | A | Issue No. | 16 (cont) | |
| LM End | 0.00 | Issue Type + | Ma | Location * | | |
| Category | Pump Stations | | | GPS Latitude/Longitude | | |
| | | | | Start | End | |
| Item | Electric Gate Operators | | | 37.773864 ° | 37.773864 ° | |
| | | | | -121.298430 ° | -121.298430 ° | |
| DWR ID | DWR_RD2096_56_t_2012_16 | | | | | |
| Action/Comments | | | | | | |
| Inspector Comments: Item appears to be in good working condition. Radial arm gate was open at time of inspection. | | | | | | |

Photo 3 of 3 : ST_2016_RD2096_56_16_20160729_00026.jpg



View of the electric gate operation mechanism.

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 17 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Manual Gate Operators | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_17 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: The LMA has the ability to engage the manual system should electric operation fail. | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_17_20160729_00020.jpg



View of the manual gate operation control.

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 18 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Other Metallic Items | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_18 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Other exposed metal items are painted or coated to prevent corrosion. | | | | | |

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | |
|--|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 19 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Flap Gates | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_19 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Flap gates appear to be fully operational. | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_19_20160729_00021.jpg



View of the flapgates.

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 20 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Closure Structures | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_20 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Radial arm gate acts as closure structure, gate was open at time of inspection. | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_20_20160729_00022.jpg



Radial arm gate, shown in open position.

| | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|
| LM Start | 0.00 | Rating ** | A | Issue No. | 21 |
| LM End | 0.00 | Issue Type + | Ma | Location * | |
| Category | Pump Stations | | | GPS Latitude/Longitude | |
| | | | | Start | End |
| Item | Security Fencing | | | 37.773864 ° | 37.773864 ° |
| | | | | -121.298430 ° | -121.298430 ° |
| DWR ID | DWR_RD2096_56_t_2012_21 | | | | |
| Action/Comments | | | | | |
| Inspector Comments: Security fencing is in place. Closed circuit cameras are also in place. | | | | | |

Photo 1 of 2 : ST_2016_RD2096_56_21_20160729_00024.jpg



View of the security cameras at the facility.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2016

Reclamation District No. 2096 Wetherbee Lake

| Structure | Structure Length | Inspection Start/End | Inspector |
|--|------------------|--------------------------|------------------|
| Wetherbee Lake Pumping Plant & Navigation Gate | | 07/21/2016 07/21/2016 | Maksim Khashchuk |

| | | | | | | |
|---|-------------------------|--------------|----|------------------------|---------------|--|
| LM Start | 0.00 | Rating ** | A | Issue No. | 21 (cont) | |
| LM End | 0.00 | Issue Type + | Ma | Location * | | |
| Category | Pump Stations | | | GPS Latitude/Longitude | | |
| | | | | Start | End | |
| Item | Security Fencing | | | 37.773864 ° | 37.773864 ° | |
| | | | | -121.298430 ° | -121.298430 ° | |
| DWR ID | DWR_RD2096_56_t_2012_21 | | | | | |
| Action/Comments | | | | | | |
| Inspector Comments: Security fencing is in place. Closed circuit cameras are also in place. | | | | | | |

Photo 2 of 2 : ST_2016_RD2096_56_21_20160729_00023.jpg



View of the security fencing around the facility.

| | | | | | | |
|---|----------------------------|--------------|----|------------------------|---------------|--|
| LM Start | 0.00 | Rating ** | A | Issue No. | 22 | |
| LM End | 0.00 | Issue Type + | Ma | Location * | | |
| Category | Pump Stations | | | GPS Latitude/Longitude | | |
| | | | | Start | End | |
| Item | Intake and Discharge Pipes | | | 37.773864 ° | 37.773864 ° | |
| | | | | -121.298430 ° | -121.298430 ° | |
| DWR ID | DWR_RD2096_56_t_2012_22 | | | | | |
| Action/Comments | | | | | | |
| Inspector Comments: Pipes appear to be free of defects. | | | | | | |

Photo 1 of 1 : ST_2016_RD2096_56_22_20160615_00013.jpg



View of the siphon breakers at the levee crown.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement